

SECRET

OUT-68067

25 JUL 69 20 05Z

SECRET 251942Z JUL 69 CITE [REDACTED] 6708

25X1
25X1

1. [REDACTED] HAVE ADVISED ME THE FOLLOWING. STUDY OF PRELIMINARY REPORT GIVES LITTLE INDICATION OF CAUSE OF RECTIFIER TROUBLE. ONLY SUGGESTION AT PRESENT IS THAT MIRROR MAY BE OUT OF ADJUSTMENT. THE COMPREHENSIVE REPORT, SAID TO FOLLOW SIGNAL, IS STILL AWAITED AND THIS SHOULD ASSIST IN DIAGNOSIS OR INDICATE FURTHER TESTS REQUIRED. ORIGINAL SETTING UP ACTION HAS NOW BEEN SUPERSEDED BY PROCEDURES WHICH HAVE NOT YET BEEN DOCUMENTED. HOWEVER, THIS DATA WOULD BE USELESS WITHOUT THE NECESSARY CALIBRATION EQUIPMENT.

25X1

2. I HAVE FORWARDED TODAY IN EMBASSY POUCH THE NEW WHEEL DRIVE WHICH SHOULD ELIMINATE SOME VIBRATION. HOWEVER, I REGRET NO FURTHER PROGRESS CAN BE MADE UNTIL FULL REPORT RECEIVED FROM [REDACTED] IF THIS BECOMES AVAILABLE DURING MY ABSENCE ON LEAVE. SUGGEST IT BE ADDRESSED TO [REDACTED] WHO WILL FORWARD IT TO [REDACTED]

25X1

SECRET

--END OF MESSAGE--

DISTRIBUTION		
CY	OFFICE	PI
/	FILE	
	CABLE SEC.	
	PF&B/RD	
	SECUR.	
	TSSG	
2	TCD	
	PSG/OC	
	RRD	
	REPRO	
	AID	
	IEG	
	PROD	
	SCIEN	
	WEST	
	EAST	
	M&S	
	PGM	
	IAS	
	DIA-XX4	
	SPAD	
	DIA-AP	
3	[REDACTED]	25X1
	CMX	

25X1

SECRET

GROUP 1
Excluded from automatic
downgrading and
declassification